

Product/Process Change Notification

| | | 1140. | | | | | | | |
|--|-----------------|----------------------------------|-------------|--------------------------------|----------|------------|-------------|-----------|--|
| PCN Number: | 100017-A | Product C | ategory: In | ker Hardwa | ire | Issue Date | e: 14-Aug-1 | 5 | |
| Contact: | Inside Sales | | | E-Mail: insidesales@xandex.com | | | | | |
| | 1360 Redwood | Way, Suite A Phone: 707-763-7799 | | | | | | | |
| | Petaluma, CA | 94954 | | Fax: 707-7 | 63-2631 | | | | |
| Description of (| Change to Cus | tomer: | | | | | | | |
| Unit redesigned to use new external power supply; new sheet metal and printed circuit boards. | | | | | | | | | |
| | | | | | | | | | |
| Reason For Change: | | | | | | | | | |
| Internal power supply components are no longer available; redesigned with external power supply. | | | | | | | | | |
| | | | | | | | | | |
| Customer Impact of Change and Recommended Action: | | | | | | | | | |
| Customers are advised to verify operation with their current usage model. | | | | | | | | | |
| | | | | | | | | | |
| Forecasted Key Milestones: Subject to change based on business conditions | | | | | | | Date: | | |
| Complete Internal Qualification Testing Complete | | | | | | | | nplete | |
| Samples Available To Order 5-Oct-15 | | | | | | | | | |
| First Shipment of Changed Product (as early as) | | | | | | | | 14-Dec-15 | |
| Last Shipment of Unchanged Product (subject to material availability) | | | | | | | | 14-Mar-16 | |
| Method of Identifying Changed Product: | | | | | | | | | |
| Serial number, revision, appearance | | | | | | | | | |
| | | | | | | | | | |
| Assessment: | | | | | | | | | |
| Change in form, Motorized Z version also changes fit (shorter in depth) | | | | | | | | | |
| | | | | | | | | | |
| Products and X | andex Part Nu | mbers Affe | cted | | | | | | |
| Pneumatic Contr | oller | 350-0002 | 350-0013 | 350-0018 | 350-0022 | 350-0023 | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| The following SK | | 340-0101 | 340-0901 | 340-1100 | 340-1101 | 340-1103 | 340-1105 | 340-1200 | |
| affected Pneuma | atic Controller | 340-1205 | 340-1206 | 340-1410 | 340-1411 | 340-1412 | 340-4112 | 340-4115 | |
| assembly | | 340-4116 | 340-4215 | 340-4216 | 340-4117 | 340-5100 | 340-5200 | 340-5210 | |
| | | | | | | | | | |
| Revision History | | | | | | | | | |
| Date of Revision | n: | Revision | Letter: | Reason: | | | | | |
| 14-Aug-15 | | | A | Initial publi | ication | | | | |
| 1 | | | | • | | | | | |

Please contact your Xandex sales representative for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.

PCN 100017-A Appendix: Qualification Testing

| Test | Result |
|--|--------|
| Safety Certification Testing: IEC 61010-1 | Pass |
| EMC Certification Testing: FCC Part 15, EN 61326-1 | Pass |
| Functional Testing | Pass |