

PCN Number:	100018-B	Product Category	: Inker Hardware	Issue Date: 9-Nov-15		
Contact:				idesales@xandex.com		
	1360 Redwood Way, Suite A		Phone: 707-763-7799			
	Petaluma, CA	94954	Fax: 707-763-263	1		
Description of	Change to Cus	tomer:				
Actuator mechar	nism redesigned	d to reduce the force	required to actuate.			
Reason For Cha						
Improve reliabilit	ty and increase	period between requ	uired Preventative Main	ntenance actions.		
	-	Ind Recommended				
Verify actuator mechanism does not impact specific customer use model.						
			sed on business cond			
Complete Internal Qualification Testing						
Samples Available To Order Now						
First Shipment of Changed Product (as early as)9-Feb-16Last Shipment of Unchanged Product (subject to material availability)8-Feb-16						
			material availability)	8-Feb-16		
Method of Iden						
Visually different	t (see accompai	nying pictures)				
Assessment:	an (antion tion ti					
Change in functi	on (actuation tir	me), form (see aco	ing proces			
Droducto and V	andox Port Nu	mboro Affostor				
Products and Xandex Part Numbers Affected Retrofit Cartridge Holder 315-0008 315-10 315-0 1						
Relibilit Cartiluge		315-0008 315-	0 315-0 1			
Revision Histor	(V					
Date of Revisio		Re. ion Letter:	Reason:			
9-Nov-15		A		Initial publication		
15-Dec-16				Cancelled PCN; design change will not be implemented		
10 200 10						
		·				
Please	our Xandex al	es re resentative for	r any questions or sup	port requirements. Please return any		
resprese as soo		out to exceed 30		·····		
			, -			
PC 00018-A A	Appender Qua	lification Testing				
	st			Result		
		ation Testing		Pass		
	In Contraction	-		Pass		
		3				